

Recordable Incidents Report: Water Bore Monitoring Program EP161 – Tanumbirini South, Inacumba North and Inacumba South Environmental Management Plan (EMP) (Ref: E2018/0024-0010)

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the Petroleum (Environment) Regulations for the Water Bore Monitoring Program EP161 – Tanumbirini South, Inacumba North and Inacumba South Environmental Management Plan (EMP) (Ref: E2018/0024-0010). This report covers the period **1 April 2021 to 30 June 2021**.

| SUMMARY OF RECORDABLE INCIDENTS UNDER SECTION 35 PETROLEUM (ENVIRONMENT) REGULATIONS QUARTERLY REPORTING FOR PERIOD 1/04/2021 TO 30/06/2021 | | | | | | | |
|--|-----------------|------------------|---|--------------------|---|--|------------------------------|
| ENVIRONMENT MANAGEMENT PLAN – Water Bore Monitoring Program – Tanumbirini South, Inacumba North and Inacumba South (E2018/0024-0010) | | | | | | | |
| Incident Date (dd/mm/yy) | Area / Location | Incident Summary | Actual Consequence (From Risk Assessment) | Corrective Actions | Relevant Environment Performance Standard | Effect on Relevant Environmental Outcome | Other Regulator Notification |
| Nil | Nil | Nil | Nil | Nil | Nil | Nil | Nil |