

Recordable Environmental Incident Summary



Northern Territory Drilling Campaign – Environment Management Plan

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the Petroleum (Environment) Regulations. During the period from 1 April to 30 June 2021, there was one recordable incident.

| SUMMARY OF RECORDABLE INCIDENTS UNDER SEC 35 PETROLEUM (ENVIRONMENT) | | | | | | | |
|--|-----------------|--|---|---|---|--|-----------------------------------|
| QUARTERLY REPORTING PERIOD – 1 April to 30 June 2021 | | | | ENVIRONMENT MANAGEMENT PLAN – NT Drilling Campaign | | | |
| Incident date | Area / location | Incident summary | Actual consequence (from risk assessment) | Corrective actions | Relevant Environment Performance Standard | Effect on Relevant Environmental Outcome | Additional Regulator Notification |
| 16 June 2021 10am | WM27 | During an inspection it was identified that the drill sump liner had slipped which resulted in a small amount of mud being spilt to grade. | Minor | <u>Immediate</u> - Rectification works were undertaken to stabilise the existing liner. - An additional high-density polyethylene liner has been placed in position to ensure all fluids are retained in the sumps. <u>Additional</u> - Once drilling is complete any potentially impacted soil will be removed, and the area remediated. | No releases of contaminants | Negligible impact. | n/a |