

Quarterly Summary Report about recordable incidents under Sec 35 Petroleum (Environment) Regulations

SUMMARY OF RECORDABLE INCIDENTS UNDER SEC 35 PETROLEUM (ENVIRONMENT) REGULATIONS QUARTERLY REPORTING FOR PERIOD 15/06/2020 TO 15/09/2020							
ENVIRONMENT MANAGEMENT PLAN – Kyalla 117 N2 Drilling, stimulation and well testing EMP NT-2050-15-MP-025							
Incident date (dd/mm/yy)	Area / location	Incident summary	Actual consequence (from risk assessment)¹	Corrective actions	Relevant Environment Performance Standard	Effect on Relevant Environmental Outcome	Other Regulator notification
08/07/2020	Kyalla 117 N2 Lease pad	It was identified during a DENR inspections that hydraulic oil had leaked into a bund (no spill to the ground). The spill kit onsite was locked in a container and not accessible by the contractor completing routine inspections to respond to the spill.	No environmental impact as the initial spill had been contained within the bund.	<ul style="list-style-type: none"> The spill kit has been moved to an accessible position. Spill kit access will be added to the demobilisation checklist for unmanned operations. 	Spill management plan implemented	No impact on the environmental outcome as no environmental harm had occurred.	N/A