

Quarterly Recordable Incident Report



Please check the following boxes if applicable to this report

Nil Incident Report:

Interest holder name:	Imperial Oil and Gas	Titleholder business address:	Level 19, 20 Bond Street, Sydney, NSW 2000	Title of environment management plan for the activity:	2021-2025 EP187 Work Program NT Exploration Permit (EP) 187 (IMP4-3), dated July 2021
Activity type: (e.g. drilling, seismic, HF, production)	Seismic, Drilling, Hydraulic Fracturing	Quarter, Year:	Q1 1/07/2022 to 30/09/2022	Title details: (e.g. Exploration Permit no., Production License no.)	EP187

Incident date	All material facts and circumstances	Environmental outcome Or performance standard breached OR Environmental impact or risk not specified in the approved EMP	Immediate action taken to avoid or mitigate any adverse environmental impacts or risks of the incident, including actions to stop or control the incident	Corrective action taken, or proposed, to prevent a similar incident occurring in future
21/09/22	No visible freeboard marker observed on the Hydrera wastewater treatment tank on Carpentaria-2 wellpad	<p><u>Measurement criteria:</u> All tanks marked with freeboard levels as per seasonal requirements</p> <p><u>Environmental Performance Standard:</u> Freeboard for all pits, Flowback Water and Produced Water tanks maintained at all times</p>	<ul style="list-style-type: none"> Visual marking instrument installed. No adverse environmental impact occurred. No direct breach of environmental performance standard occurred. 	Process reviewed for tank liner re-installation.
21/09/22	Fire access trail observed to contain topsoil stockpile at the under-construction Carpentaria-4 wellpad.	<p><u>Measurement Criteria:</u> Implementation of Fire Management Plan (Appendix 08) (Section 8.5 The wellpads are designed with a ring fire access trail/fire break ~30m from the fenceline)</p> <p><u>Environmental Performance Standard:</u> No fires in surrounding areas resulting from conduct of the regulated activity</p>	<ul style="list-style-type: none"> Top soil stockpile removed from fire access trail. No adverse environmental impact occurred. No direct breach of environmental performance standard occurred. 	Review firebreak requirements during construction of wellpads. Review firebreak purpose within EMP.