

Quarterly Recordable Incident Report



Please check the following boxes if applicable to this report:

Nil Incident Report:

Interest holder name:	Imperial Oil and Gas	Titleholder business address:	Level 5, 6-10 O'Connell Street, Sydney, NSW 2000	Title of environment management plan for the activity:	IMP 1-3 2D Seismic Work Program EP 187
Activity type: (e.g. drilling, seismic, HF, production)	Seismic	Quarter, Year:	Q2, 1/04/2023 to 30/06/2023	Title details: (e.g. Exploration Permit no., Production License no.)	EP 187

Incident date and time	All material facts and circumstances	Environmental outcome Or performance standard breached OR Environmental impact or risk not specified in the approved EMP	Immediate action taken to avoid or mitigate any adverse environmental impacts or risks of the incident, including actions to stop or control the incident	Corrective action taken, or proposed, to prevent a similar incident occurring in future
9/5/23	Imperial received correspondence from Hon Lauren Moss, rejecting Imperial's Regulation 14 closure notice for EMP IMP1-3 (submitted 27 October 2022). The correspondence states that, in the Ministers view, 'Imperial has not demonstrated compliance with Approval Conditions 3 and 4'.	EMP Section 7.5.1.8 Performance Objective: <i>"ensure that rehabilitation is compatible with existing land use and meets the expected standards of the community"</i>	Gap analysis of rehabilitation events initiated.	Imperial acknowledges that there is an ongoing discussion regarding Imperial's Regulation 14 closure notice for EMP IMP1-3. Imperial will continue to investigate the concerns highlighted in the correspondence received. This item has been included in the Q2 Quarterly Recordable Incident Report 2023 to reflect the ongoing discussion of this item.