

Quarterly Recordable Environmental Incident Report



Mereenie Field Workover and Wellhead Equipment, Safety Systems and Gathering Line Activities – Environment Management Plan

The following information has been compiled to satisfy the reporting requirements for recordable incidents under Part 3, Division 1, Regulation 35 of the *Petroleum (Environment) Regulations 2016* for the period 01 January 2022 to 31 March 2022.

| Nil Incident Report <input checked="" type="checkbox"/> | | | | | |
|---|--|--------------------------------------|---|---|--|
| Interest Holder Name: | <ul style="list-style-type: none"> Central Petroleum Mereenie Pty Ltd Macquarie Mereenie Pty Ltd | Title holder business address | <ul style="list-style-type: none"> Level 7, 369 Ann Street Brisbane Qld 4000 Level 6 / 50 Martin Place, Sydney, NSW, 2000 | Title of environmental management plan for the activity: | Mereenie Field Workover and Wellhead Equipment, Safety Systems and Gathering Line Activities |
| Activity type: | Production | Quarter, Year | Quarter 1, 2022 | Title details: | Operating Licence 4 Operating Licence 5 |

| SUMMARY OF RECORDABLE INCIDENTS UNDER SEC 35 PETROLEUM (ENVIRONMENT) REGULATION | | | | |
|---|--------------------------------------|--|--|---|
| Incident date and time | All material facts and circumstances | Environmental outcome(s) and/or performance standard(s) breached OR environmental impact or risk not specified in Approved EMP | Immediate Action taken to avoid or mitigate any adverse environmental impacts of risk of the incident, including actions to stop or control the incident | Corrective action taken, or proposed, to prevent similar incident occurring in future |
| | | | | |